

Table 1. PRELIMINARY Legionella Water Testing Results

Lane Community College - Eugene, Oregon
Various Buildings & Fixtures

| Building* | Floor* | Fixture* | Location* | Test Kit Serial Number | Results (MPN/100mL) ¹ |
|-----------|--------|----------|------------------------|------------------------|----------------------------------|
| Center | 1st | 10 | 101C Dougs | 111397 | 1460 |
| Center | 1st | 16 | Student Microwave Area | 111667 | 175 |
| Center | 2nd | 3 | 200G Coffee Area | 111342 | 142 |
| Center | 2nd | 1 | 207 Mothering Room | 111371 | 328 |
| Center | 3rd | 1 | 328 Break Room | 111613 | 422 |
| Center | 3rd | 3 | 311 Academic Testing | 111647 | 18 |
| Center | 4th | 1 | 404 Staff Lounge | 102863 | 79 |
| Center | 4th | 2 | 448 Staff Lounge | 111573 | 22 |
| 1 | 1st | 1 | 126 Work Room | 111319 | 2 |
| 1 | 1st | 2 | 115A Work Room | 111591 | 169 |
| 1 | 2nd | 1 | 201 Student Activities | 110965 | 318 |
| 1 | 2nd | 4 | 212 Conference Room | 111312 | ND |
| 2 | 1st | 1 | 112 Break Room | 111547 | ND |
| 3 | 1st | 1 | 121 HR Kitchen | 110982 | 1 |
| 3 | 2nd | 1 | 216A Coffee Room | 111542 | 3 |
| 4 | 1st | 1 | 104 | 110959 | ND |
| 4 | 1st | 2 | 123 Archives | 111335 | ND |
| 4 | 2nd | 1 | 232 Break Room | 111577 | 1 |
| 5 | 1st | 1 | 102 | 111437 | 449 |
| 5 | 1st | 3 | 125 | 111467 | 1920 |
| 5 | 2nd | 2 | 206A | 106968 | ND |
| 5 | 2nd | 3 | 222 Lounge | 111328 | 62 |
| 7 | 1st | 1 | 106 Break Room | 110987 | ND |
| 7 | 2nd | 3 | 222 | 110981 | 47 |
| 7 | 2nd | 1 | 209 | 110989 | ND |
| 8 | 1st | 1 | 117 Conference Room | 110999 | ND |
| 8 | 1st | 3 | 101 Dental | 110951 | ND |
| 10 | 1st | 12 | 108 | 110991 | 7 |
| 10 | 1st | 6 | 131 Work Room | 111600 | ND |
| 10 | 2nd | 1 | 207 Marketing | 111327 | ND |
| 11 | 1st | 2 | 136 Work Room | 111338 | ND |

| Building* | Floor* | Fixture* | Location* | Test Kit Serial Number | Results (MPN/100mL) ¹ |
|-----------|--------|----------|--------------------|------------------------|----------------------------------|
| 11 | 1st | 1 | 101 Work Room | 111670 | 2 |
| 11 | 2nd | 1 | 245C Work Room | 102860 | ND |
| 11 | 2nd | 2 | 226 Staff Lounge | 111304 | 2 |
| 12 | 1st | 2 | 121 Break Room | 111501 | 712 |
| 15 | 1st | 1 | 106 Break Room | 111336 | 8 |
| 16 | 1st | 52 | 115 | 111391 | ND |
| 16 | 1st | 3 | 164 Work Room | 111541 | 134 |
| 16 | 2nd | 1 | 205 Lunchroom | 107392 | 2 |
| 16 | 2nd | 3 | 271 | 111314 | 1 |
| 17 | 1st | 1 | 101 Lobby | 111354 | 872 |
| 18 | 1st | 1 | 107 | 106962 | 196 |
| 18 | 1st | 24 | 109 Break Room | 106964 | 477 |
| 18 | 2nd | 1 | 205 Work Room | 111492 | 1 |
| 19 | 1st | 4 | 114 Kitchen | 111588 | ND |
| 19 | 1st | 16 | 143 Work Room | 111628 | 555 |
| 19 | 2nd | 2 | 231H Work Room | 106999 | 13 |
| 19 | 2nd | 4 | 266B Lounge | 111672 | 4 |
| 30 | 1st | 1 | 116 Student Lounge | 111623 | ND |
| 30 | 1st | 9 | 135 | 107406 | ND |
| 30 | 2nd | 1 | 243 | 111316 | 131 |
| 30 | 2nd | 9 | 219 | 111090 | 1460 |
| 31 | 1st | 2 | 103 Kitchen | 110973 | ND |
| 61 | 1st | 1 | 108 | 110995 | ND |
| 61 | 1st | 6 | 131 Break Room | 110972 | ND |
| 61 | 2nd | 4 | 227 Break Room | 102854 | ND |
| 61 | 2nd | 5 | 208 Work Room | 111332 | ND |
| 61 | 3rd | 6 | 326 Break Room | 110974 | ND |
| 61 | 3rd | 7 | 311 Work Room | 110992 | ND |
| 61 | 4th | 1 | 427 Break Room | 110975 | ND |
| 61 | 4th | 2 | 407 Work Room | 111479 | ND |

NOTES:

* Denotes location data provided by LCC staff

¹ MPN/100mL = Most Probable Number of viable cells in cultured sample dilution per 100 milliliters of sampled water

= Sample result at or very near laboratory detection limit, minor action likely necessary

= Sample result well above laboratory detection limit, significant action likely necessary