

Chlorine Testing

Building	Room Number	Description	Results	Temp	Date
08	117	Conference	.26	67°	07/29/21
09	107	Push Bottle Fill	.25	68°	07/29/21
10	112	Push Bottle Fill	.28	66°	07/29/21
10	210	Push Bottle Fill	.28	67°	07/29/21
11	105	Bottle Fill	.31	61°	07/29/21
11	200A	Bottle Fill	.29	60°	07/29/21
12	119c	Break Room	.27	66°	07/29/21
12	219	Break Room	.24	66°	07/29/21
00	448	Staff Lounge	.43	68°	08/02/21
00	325	Bottle Fill DF	.39	67°	08/02/21
00	207	Bottle Fill DF	.33	65°	08/02/21
00	120	Push Bottle Fill	.27	68°	08/02/21
00	001c	Bottle Fill DF	.28	64°	08/02/21
16	205	Lunch Room	.26	68°	08/02/21
16	100G	Push Bottle Fill	.31	67°	08/02/21
24	111	work Room	.23	68°	08/02/21
25	206B	changing Sink	.22	69°	08/02/21
26	316	Entry Sink	.24	68°	08/02/21
27	415	Class sink	.22	68°	08/02/21
07	106	Break Room	.29	67°	08/03/21
07	209	work Room	.31	68°	08/03/21
06	100D	Push Bottle Fill	.36	67°	08/03/21
06	200A	Push Bottle Fill	.39	66°	08/03/21
30	115	Push Bottle Fill	.26	70°	08/03/21
30	214	Push Bottle Fill	.22	69°	08/03/21
05	241	Push Bottle Fill	.36	66°	08/03/21
05	101	Bottle Fill	.38	68°	08/03/21
17	101	Lobby Faucet	.33	68°	08/03/21
01	100A	Bottle Fill	.31	66°	08/04/21
01	206	Room Faucet	.39	68°	08/04/21
02	112	Break Room	.40	68°	08/04/21
03	108A	Break Room	.32	67°	08/04/21
03	200	Push Bottle Fill	.34	69°	08/04/21
04	104	Class Sink	.32	68°	08/04/21
04	004K	Push Bottle Fill	.28	67°	08/04/21
31	110	Push Bottle Fill	.25	65°	08/04/21
19	100D	Push Bottle Fill	.31	67°	08/04/21
19	200A	Bottle Fill	.34	64°	08/04/21

