

Chlorine Testing

Building	Room Number	Description	Results	Date
LCC00	448	staff lounge	.24	11-01-21
LCC00	311	resting sink	.23	11-01-21
LCC00	207	mothering	.23	11-01-21
LCC00	101E	East Sink	.25	11-01-21
LCC00	006	storage sink	.21	11-01-21
LCC16	271	Class sink	.26	11-04-21
LCC16	144	Lounge sink	.24	11-04-21
LCC24	111	work room	.22	11-01-21
LCC25	210	changing sink	.26	11-01-21
LCC26	316	Entry sink	.26	11-01-21
LCC27	408	classroom sink	.24	11-01-21
LCC31	103	N Kitchen Sink	.27	11-01-21
LCC05	155	Bottle Fill	.22	11-02-21
LCC05	222	Lounge	.24	11-02-21
LCC06	100D	Bottle Fill	.28	11-02-21
LCC06	200B	Bottle Fill	.24	11-02-21
LCC07	106	Break Room	.25	11-02-21
LCC07	212	Break Room	.29	11-02-21
LCC30	115	Bottle Fill	.28	11-02-21
LCC30	214	Bottle Fill	.31	11-02-21
LCC01	126	work room	.22	11-03-21
LCC01	212	Conference	.29	11-03-21
LCC02	112	Break Room	.33	11-03-21
LCC03	200	Lobby Bottle fill	.26	11-03-21
LCC03	107A	Staff Room	.24	11-03-21
LCC04	232	Staff Room	.28	11-03-21
LCC04	104	class room	.21	11-03-21
LCC19	143	work room	.25	11-04-21
LCC19	200E	Bottle Fill	.29	11-04-21
LCC18	107	classroom	.26	11-04-21
LCC18	205	work room	.25	11-04-21
LCC17	101	Lobby	.22	11-04-21
LCC15	106	Break Room	.21	11-04-21
LCC15	200	Bottle Fill	.24	11-04-21
LCC08	117	Conference	.21	11-05-21
LCC09	101	Drinking fount	.23	11-05-21
LCC11	245C	work room	.20	11-05-21
LCC11	101	work room	.21	11-05-21

