

## Chlorine Testing

Building	Room Number	Description	Results	Date
LCC49	101	Lounge	.51	Sept. 30, 2021
LCC49	124	staff lounge	.47	Sept 30, 2021
LCC00	404	staff lounge	.29	Oct. 4, 2021
LCC00	325	workroom	.29	oct. 4, 2021
LCC00	207	mothering	.30	oct. 4, 2021
LCC00	101A	Grill sink	.27	oct. 4, 2021
LCC00	006	<del>Break</del> Storage	.32	oct. 4, 2021
LCC16	217	Conference	.27	oct. 4, 2021
LCC16	193	work room Rt	.29	oct 4, 2021
LCC24	122	student Break	.23	oct 4, 2021
LCC25	207	work room	.25	oct 4, 2021
LCC26	304	Entry Sink	.22	oct 4, 2021
LCC27	418	Kitchen West	.27	oct 4, 2021
LCC61	122	Bottle Fill	.42	oct 4, 2021
LCC61	223	Bottle Fill	.45	oct 4, 2021
LCC61	322	Bottle Fill	.37	oct 4, 2021
LCC61	423	Bottle Fill	.43	oct 4, 2021
LCC05	102	checkout Faucet	.30	oct 5, 2021
LCC05	201	DF Bottle Fill	.29	oct 5, 2021
LCC06	100D	DF Bottle Fill	.36	oct 5, 2021
LCC06	200B	DF Bottle Fill	.32	oct 5, 2021
LCC07	106	Break Room	.28	oct 5, 2021
LCC07	209	work room	.27	oct 5, 2021
LCC30	115	DF Bottle Fill	.22	oct 5, 2021
LCC30	214	DF Bottle Fill	.25	oct 5, 2021
LCC17	101	Lobby Sink	.28	oct 5, 2021
LCC15	106	Break Room	.24	oct 5, 2021
LCC15	200	DF Bottle Fill	.27	oct 5, 2021
LCC01	115A	work room	.25	oct 6, 2021
LCC01	201	VETS Sink	.23	oct 6, 2021
LCC02	112	Break Room	.26	oct 6, 2021
LCC03	216a	Coffee Room	.26	oct 6, 2021
LCC03	121	work room	.30	oct 6, 2021
LCC04	232	Break Room	.25	oct 6, 2021
LCC04	104	classroom	.23	oct 6, 2021
LCC31	103	E Kitchen Faucet	.28	oct 6, 2021
LCC19	107	N Staging Sink	.21	oct 6, 2021
LCC19	200E	DF Bottle Fill	.23	Oct 6, 2021

