

## Chlorine Testing

Building	Room Number	Description	Results	Date
LCC49	130	Classroom	.24	Sept 02, 21
LCC49	133	work room	.29	Sept 02, 21
LCC61	176	CC Area	.37	Sept. 02, 21
LCC61	427	Break Room	.42	Sept. 02, 21
LCC61	321	Classroom	.49	Sept 02, 21
LCC61	237	work room	.46	Sept 02, 21
00	448	Staff lounge	.35	Sept 07, 21
00	311	Testing Center	.33	Sept 07, 21
00	2006	Coffee Prep	.27	Sept 07, 21
00	006	Storage Sink	.24	Sept 07, 21
00	104	Bottle Filler	.26	Sept 07, 21
16	271	classroom	.22	Sept 07, 21
16	156D	STAFF Lounge	.26	Sept 07, 21
24	122	Break room	.28	Sept 07, 21
25	210A	changing Sink	.31	Sept 07, 21
26	316	Entry Sink	.27	Sept 07, 21
27	408	Classroom	.30	Sept 07, 21
05	115	Training Sink	.35	Sept. 07, 21
05	206A	work room	.27	Sept. 07, 21
06	1000	DF Bottle Fill	.32	Sept. 07, 21
06	200B	DF Bottle Fill	.29	Sept. 07, 21
07	106	Break Room	.30	Sept 08, 21
07	222	Break Room	.32	Sept 08, 21
30	116A	Juice BAR	.27	Sept 08, 21
30	214	DF Bottle Fill	.23	Sept 08, 21
01	100A	Bottle Filler	.21	Sept 08, 21
01	212	Conference	.32	Sept 08, 21
02	112	Break Room	.37	Sept 08, 21
03	200	DF Bottle Fill	.30	Sept 08, 21
03	121	Staff kitchen	.28	Sept 08, 21
04	232	Break Room	.36	Sept 08, 21
04	104	Class room	.31	Sept 08, 21
31	116	DF Bottle Fill	.38	Sept 08, 21
08	101	NW Faucet	.22	Sept 10, 21
09	101	DF Bottle Fill	.20	Sept 10, 21
10	131	work room	.38	Sept 10, 21
10	207	OFFICE Sink	.31	Sept 10, 21
11	100	DF Bottle Fill	.26	Sept 10, 21

