

## Chlorine Testing

Building	Room Number	Description	Results	Date
05	135	Bottle Fill DF	.22	09/06/22
05	201	Bottle Fill DF	.26	09/06/22
06	1000	DF Bottle Fill	.21	09/06/22
06	200B	DF Bottle Fill	.23	09/06/22
07	106	Break Sink	.30	09/06/22
07	212E	Break Sink	.26	09/06/22
30	131	staff lounge	.23	09/06/22
30	219	Class Sink	.21	09/06/22
31	103	E Kitchen Sink	.22	09/06/22
01	115A	work room	.28	09/07/22
01	212	Conference	.30	09/07/22
02	112	Breakroom	.24	09/07/22
03	107A	Staff room	.29	09/07/22
03	216A	Coffee Room	.28	09/07/22
04	104	Class Sink	.24	09/07/22
04	232	Staff Room	.28	09/07/22
15	106	work room	.33	09/07/22
15	206	DF Bottle Fill	.30	09/07/22
17	101	Lobby Sink	.27	09/07/22
18	100	Drinking Fountain	.21	09/08/22
18	205	work room	.24	09/08/22
19	114	W. Kitchen Sink	.28	09/08/22
19	200A	Bottle Fill DF	.23	09/08/22
08	101	S. Class Sink	.33	09/08/22
09	109	DF Bottle Fill	.36	09/08/22
10	108	Class Sink	.29	09/09/22
10	210	DF Bottle Fill	.27	09/09/22
11	131	Class Sink	.22	09/09/22
11	245c	work room	.25	09/09/22
12	119c	work room	.27	09/09/22
12	219	Breakroom	.26	09/09/22
16	271	Class Sink	.22	09/09/22
16	193	NW Sink	.21	09/09/22
00	001c	Bottle Fill DF	.27	09/12/22
00	112	Kitchen Sink N	.27	09/12/22
00	207	Bottle Fill DF	.29	09/12/22
00	328	Breakroom	.26	09/12/22
00	404	Lounge Sink	.23	09/12/22
24	122	Breakroom	.25	09/12/22

